



<b>Runways</b>		<b>Coordinates</b>	
08/26: 3200 x 40 (ASPH-F)		Latitude	42-55-20.212N
		Longitude	078-36-44.096W
<b>Communications</b>		<b>Navigation</b>	
CTAF/U	122.8	Elevation	750
		NM from City	03 NE
		Instr Approach	NONE
<b>Owner/Manager</b>		<b>Services</b>	
Owner	LANCASTER AIRPORT INC	Fuel	80 100 LL
Manager	MR THOMAS GELES	Airframe Repairs	
	10904 TOWNLINE ROAD	Engine	
	DARIEN CENTER NY 14040	Attended	CALL
Phone	(716) 683-7203	Airline Airport	NO
Fax	(716) 681-5208	Transportation	
E-mail		Food	
Web site		Lodging	
<b>FBO (Location)</b>		<b>Remarks</b>	
		WIND INDICATOR IS A WIND TEE. GRAVEL PIT 40 FT FROM RWY 8 END. RR TRACKS 150 FT S OF RWY CENTERLINE AND PARALLEL TO RWY.	